
B2150VB-055, 1-1/2", V Ball Control Valve Hardened Chrome Plated Carbon Steel Body, Stainless Steel Ball and Stem







chilled or hot water, up to 60% glycol,
steam
equal percentage
75°
1.5" [40]
NPT female ends (1"to 2"); ISO flange (3"to 6")
WCC Grade Carbon steel
stainless steel
stainless steel
spring loaded Teflon® V-ring
Teflon®
ASME/ANSI Class 300
200 psi
-22°F to 380°F [-30°C to 193°C]
-22°F to 380°F [-30°C to 193°C]
100 psi
100 psi
150 psi
100 psi
150 psi
200 psi
300:1
55
14.6 lb [6.6 kg]
ANSI Class IV



Product Features

Fast quarter turn open or closed operation, Stainless steel ball and stem, Positive shut-off, Two piece body construction

Application

Water-side control of air handling apparatus in ventilation and air-conditioning


Water/Steam control in heating system.

300:1 rangeability.

The dimensions and drilling of end flanges conform to the American cast iron flange standard, Class 150 (ANSI B16.1).

Suitable Actuators

	Non-Spring	Spring			
B2150VB-055	SY1, SY2, AMB(X)	NFB(X)			




Α	В	С	D	Е	F	H1	H2
12.81"	6.5"	13.47"	10.47"	1.81	" [46]	1.18"	0.5" [15]
[325]	[165]	[342]	[266]			[30]	


Date created, 09/01/2016 - Subject to change.

Belimo Aircontrols (USA), Inc.

B2150VB-055, 1-1/2", V Ball Control Valve Hardened Chrome Plated Carbon Steel Body, Stainless Steel Ball and Stem




Α	В	C	D	Е	F	J
6.72"	6.5" [165]	15.63"	13.03"	2.4"	[61]	21.13"
[171]		[397]	[331]			[536]



Α	В	C	D	Е	F	J
12.6"	6.5" [165]	19.38"	16.97"	4.48"	3.56" [90]	28.48"
[320]		[492.3]	[431]	[114]		[723]

B2150VB-055, 1-1/2", V Ball Control Valve Hardened Chrome Plated Carbon Steel Body, Stainless Steel Ball and Stem





Α	В	С	D	Е	F
12.74"	6.5" [165]	13.47"	10.47"	1.95	" [49]
[324]		[342]	[266]		





Technical Data	
Power Supply	120 VAC ± 10%, 50/60 Hz
Power Consumption Running	58 W
Transformer Sizing	72 VA (class 2 power source)
Electrical Connection	terminal block
Overload Protection	thermally protected 135°C cut-out
Operating Range Y	2 to 10 VDC, 4 to 20 mA w/ ZG-R01 (500 Ω, 1/4 W resistor) between 0% and 100%
Input Impedance	100 k Ω for 2 to 10 VDC (0.1 mA), 500 Ω for 4 to 20 mA
Feedback Output U	2 to 10 VDC
Angle of Rotation	90°
Torque	310 in-lbs [35 Nm] minimum
Duty cycle	75%
Direction of Rotation (Motor)	reversible with built-in switch
Position Indication	top mounted domed indicator
Manual Override	use a 8mm wrench to override
Running Time (Motor)	12 sec
Internal Humidity Control	resistive heating element
Ambient Humidity	5 to 100% RH (UL Type 4)
Ambient Temperature Range	-22°F to 150°F [-30°C to 65°C]
Storage Temperature Range	-40°F to 176°F [-40°C to 80°C]
Housing	NEMA 4X, IP66/67, UL Enclosure Type 4
Housing Material	die cast aluminum alloy
Gear Train	high alloy steel gear sets, self locking
Agency Listings†	ISO, CE, cCSAus
Noise Level (Motor)	<45 dB (A)
Servicing	maintenance free
Quality Standard	ISO 9001
Weight	5.3 lb [2.4 kg]
Auxiliary Switch	2 x SPDT 3A resistive (0.5A inductive) @ 250 VAC, one set at +10° and one set at 85°

Application

SY Series actuators are fractional horsepower devices, and utilize full-wave power supplies. Observe wire sizing and transformer sizing requirements. Proportional models CANNOT be connected to Belimo direct coupled (AF, AM, GM...etc) actuator power supplies or any type of half-wave device. You MUST use a separate, dedicated transformer or power supply to power the SY actuator. Please do not connect other automation equipment to the dedicated SY supply source. You MUST use four wires (plus a ground) to control a proportional control SY actuator (See SY Wiring Section).





Modulating, Non-Spring Return, 120 V, for 2 to 10VDC or 4 to 20 mA

Wiring Diagrams



X INSTALLATION NOTES



Do not change sensitivity or dip switch setting with power applied.



Power supply Common/Neutral and Control Signal "-"wiring to a common is prohibited. Terminals 4 and 6 need to be wired separately.



Isolation relays must be used in parallel connection of multiple actuators using a common control signal inputs. The relays should be



Isolation relays are required in parallel applications. The reason parallel applications need isolation relays is that the motor uses two sets of windings, one for each direction. When one is energized to turn the actuator in a specific direction a voltage is generated in the other due to the magnetic field created from the first. It's called back EMF. This is not an issue with one actuator because the voltage generated in the second winding isn't connected to anything so there is no flow. On parallel applications without isolation, this EMF voltage energizes the winding it is connected to on the other actuators in the system, the actuators are tying to turn in both directions at once. The EMF voltage is always less than the supply voltage due to the resistance of the windings, so while the actuator still turns in the commanded direction, the drag from the other reduces the torque output and causes overheating.



WARNING! LIVE ELECTRICAL COMPONENTS!

During installation, testing, servicing and troubleshooting of this product, it may be necessary to work with live electrical components. Have a qualified licensed electrician or other individual who has been properly trained in handling live electrical components perform these tasks. Failure to follow all electrical safety precautions when exposed to live electrical components could result in death or serious injury.

